

VOLVO ROCKER ARM 422063 NEW

Product Images



Additional Information

| | |
|----------------------|--|
| Merk | VOLVO |
| Motor Type | D10B, TD100G, TD102KH, TD1030VE, TD103KCE, TWD1031VE |
| Voorwaarde | ORIGINEEL |
| Vervangt | 422063 |
| Toepassing Geschikt: | Volvo |

| | | |
|--------------------------------------|-------------------------------------|---------------|
| Inner diameter [mm] | d | 24.6 |
| Thread Size | | 3/8" x 24 UNF |
| Vehicle brand | Model, Engine, Gearbox, Axle, Cabin | |
| Volvo Bus B 10/12 (TD/THD engine) | THD 102 K, D 10 A | |
| Volvo Bus B 5/6/7/8 | TD 73, D 7 A/B/C | |
| Volvo F/FL 6 (-2000), F/FL/FM 7, FLC | TD 71/73, D 7 A/B/C | |
| Volvo F/FL/N/NL 10/12/16 | TD 100/101, TD 102/103, D 10 A | |
| Volvo FH/FM/FMX/NH 9/10/11/12/13/16 | D 10 B | |
| | ReplacesRef. No. | |
| Vervangt ref. Nee. | Volvo | 422063 |