

SCANIA HEADLAMP 289914 NEW

Product Images



Additional Information

Brand	SCANIA
Condition	ORIGINAL
Replaces	289914
Application Suitable	Scania

Fitting Position

Right

Lamp Shape

H4

Vehicle brand

Model, Engine, Gearbox, Axle, Cabin

Scania 2-/3-Series

82, 92, 112, 142 93, 113, 143 -- chassis 1173434, -- chassis 4306438

Replaces Ref. No.

Replaces Ref. No.

Scania 289914