

SCANIA REDUNDANCY VALVE 1935138 NEW

Product Images



Additional Information

Brand	SCANIA
Condition	ORIGINAL
Replaces	004 429 9144
Application Suitable	Mercedes-Benz

Vehicle brand

Model, Engine, Gearbox, Axle, Cabin

Mercedes-Benz Actros/Antos/Arocs/Axor

Actros 1 950/952/953/954; Axor 375/940/942/943,
944/950/952/953, 954

	Replaces	Ref. No.
Replaces Ref. No.	Mercedes-Benz	004 429 9144
	Scania	1935138