

## SCANIA OIL STRAINER 1307097 NEW

### Product Images



### Additional Information

Brand	SCANIA
Condition	ORIGINAL
Replaces	1307097
Application Suitable	Scania

Vehicle brand	Model, Engine, Gearbox, Axle, Cabin
Scania 2-/3-Series	GR 801 /R, GR-GRS 900 /R, GRH 900
Scania 4-Series	GR 801 /R, GR-GRS-GRSH 900 /R, GRS 920 /R
Scania Bus 3-Series	GR 801 /R
Scania Bus 4-/F-/K-/N-Series	4-Series GR 801 /R F-/K-/N-Series GR 801 /R
Scania P-/G-/R-/T-Series	GR 801 /R, GRS 890 /R, GR-GRS 900 /R, GRS 920 /R

	<b>Replaces Ref. No.</b>
Replaces Ref. No.	Scania 1307097