

## SCANIA RADIATOR STRUT 1329883 NEW

### Product Images



### Additional Information

Brand	SCANIA
Condition	ORIGINAL
Replaces	1329883
Application Suitable	Scania
Vehicle brand	Model, Engine, Gearbox, Axle, Cabin
Scania 2-/3-Series	P 113, R 93/113/143
Replaces Ref. No.	<b>ReplacesRef. No.</b>
	Scania 1118496
	Scania 1329883