

SCANIA RADIATOR HOSE 440685 NEW

Product Images



Additional Information

Brand	SCANIA		
Condition	ORIGINAL		
Replaces	440685		
Application Suitable	Scania		
Inner diameter 1 [mm]	dl	4	4.5
Inner diameter 2 [mm]	d2	5	5
Vehicle brand	Model, Engine, Gearbox, Axle, Cabin		
Scania Bus 3-Series	K 113		
Replaces Ref. No.	Replaces Ref. No. Scania 440685		