

SCANIA FILLER CAP 385075 NEW

Product Images



Additional Information

Brand	SCANIA	
Condition	ORIGINAL	
Replaces	1424756	
Application Suitable	Scania	
Diameter [mm]	D	80
Vehicle brand	Model, Engine, Gearbox, Axle, Cabin	
Scania 2-/3-Series	93, 113, 143	
Scania 4-Series	94, 114, 124, 144, 164	
Scania Bus 3-Series	F/K 93, F/K/L/N 113	
Scania P-/G-/R-/T-Series	PDE -- chassis 2022159, -- chassis 5161834, -- chassis 9115701, -- chassis 3598108	
	ReplacesRef. No.	
Replaces Ref. No.	Scania	1424756
	Scania	385075