

SCANIA FILLER CAP 385075 NEW

Product Images



Additional Information

Marca	SCANIA
Condición	ORIGINAL
Reemplaza	1424756
Aplicación adecuada	Scania

Diameter [mm] D 80

Vehicle brand Model, Engine, Gearbox, Axle, Cabin

Scania 2-/3-Series 93, 113, 143

Scania 4-Series 94, 114, 124, 144, 164

Scania Bus 3-Series F/K 93, F/K/L/N 113

Scania P-/G-/R-/T-Series PDE -- chassis 2022159, -- chassis 5161834, -- chassis 9115701, -- chassis 3598108

ReplacesRef. No.

Reemplaza ref. No. Scania 1424756

Scania 385075