

IVECO 8061 SI 13.05 ?/?



???????????????????

????? ??????:

PRJB2018122271

?????????:

?/?

?????:

iveco

????????? ?????? ??????????:

577560

???:

????????? ??????????

??? ????????:

?????????

????? ??????????

red

????? ?????????? SAE

sae 3

????? SAE

sae 10

Working Hours	250 hour(s)
?????????? ??????????	core
?? ???? ????????????	dry
?? ??????????? ??????????	radiator cooled (std)
?????? ?????????????? ?????? ?????????? (no
????????? ??????????	24 volt
????? (??????????/???????????)	900 kg
?? ????????	mechanical fuelpump
????????? ????????	dry
??????	100 cm
??????	125 cm
????? ????????	125 cm
?? ????????????????	1010